


# Specifications

Models 471/481 SLMAC/SLMC

Electrical connections		471/481 SLMAC/SLMC	
Voltage 120V 1PH 50/60Hz .5amps		Standard	
Voltage 230V 1PH 50/60Hz .25amps		optional	
Optional Iron Attachment:			
Voltage 120V 1PH 50/60Hz		Wattage	1000
Approx. Consumption/hour			0.5 KWH
Steam and Air connection			
Steam Inlet	NPT	1/2"	
Steam Outlet	NPT	1/2"	
Rec. steam pressure	PSIG	75-85	
	kPa	517-586	
Steam consumption @ 80psig(552 kPa)	lb/hr	51.8	
	kg/hr	23.5	
Compressed air	NPT	3/8"	
Air consumption	free air/cycle at 80psig	0.32 FT <sup>3</sup>	
	free air/cycle at 552kPa	.009m <sup>3</sup>	
Rec. air pressure	PSIG	80	
	kPa	552	
Air Vacuum Connection	NPT	1 1/4"	
Weight (crated)			
Shipping	471/481 SLMAC	lbs	850
		kg	386
	471/481 SLMC	lbs	822
		kg	373
1 Control Push Buttons		4 Steam Outlet connection	
2 Steam connection		5 Air Vacuum Connection	
3 Air connection		6 Electrical Connection	



## Detail Line Drawing (millimeters shown in parentheses)

